

#336 – 2389 Health Sciences Mall, Vancouver BC V6T 1Z3
Phone: 604-822-2029
WorkSafeBC Account # 11284

# **Standard Investigation Report**

# Incident ID: 129773 (Supervisor Report)

## **Incident Information**

Incident Details, Description and Sequence of Events

#### Incident Title:

Ice falling from ceiling

Date:	Time:	Building:
Aug 16, 2022	2:00 PM	<b>BIO</b> - Biological Sciences
		Building

Description of Incident Location (please do not include personal information such as names, gender pronouns and medical information):

AC unit on ceiling dropped roughly 20 lbs of ice, almost hitting undergrad on the head.

Accident Type:	Injury Type:
Equipment/Facility Failure (No Injuries)	No Injuries

Describe fully what happened before, during, and after the incident (please do not include personal information such as names, gender pronouns and medical information):

Yesterday, August 15, 2022, I noticed ice build up on the AC unit and created a service request on the same day. Today, August 16, 2022, the ice fell and almost hit someone in the head.

## **Accident Investigation**

Task Related Causes
_

No "Task" Causes

#### **Environment Related Causes**

**Other (specify below)** 

Other environmental causes:

Faulty AC unit

Equipment Related Causes		
	Preventative maintenance / inspections inadequate	Material / equipment failure

# Organizational Related Root Causes

No "Organizational" related causes



#336 – 2389 Health Sciences Mall, Vancouver BC V6T 1Z3 Phone: 604-822-2029 WorkSafeBC Account # 11284

## Human Related Root Causes

## No "Human" related causes

#### Root cause

Incorporating the above factors, determine and describe the root cause of the incident or accident:

Ice from faulty AC unit mounted to the ceiling fell as it melted.

## Persons who carried out or participated in the investigation

#### **Employer representative name:**

Eric Lotto

Job title:

**Facilities Technician** 

# Worker Representative Name:

# Dolph Schluter

Job title:

Professor

## **Corrective Actions**

## **Corrective Action to prevent recurrence of similar incidents (1)**

### **Corrective Action Identified:**

Remaining ice was removed from AC unit to prevent more ice from falling. Room users were told to be aware of AC unit and facility technician has been checking for ice daily. We are still waiting for plant ops to get back to us to make sure that ice is not left on broken AC units, especially when they are turned off.

Assigned to (name):	Job title:
Eric Lotto	Facility Technician

## Final Actions Taken:

Remaining ice was removed from AC unit to prevent more ice from falling. Room users were told to be aware of AC unit and facility technician has been checking for ice daily.

Date to be Completed:	Date Completed:
2022-08-17	2022-08-17